

#3

FIG. 1




Fig. 1




Fig. 2A




Fig. 2B

```

<?xml version="1.0"?>
<!--Assembly Publishing XML-->

<TARGETFACE ID="1" NAME="Sliding Assembly" DESCRIPTION="SolidWorks
Assembly" NAVIGATIONMODE="2" SPECIALTYPE="4"><INFOITEM NAME="Sliding
Assembly Bundle" DESCRIPTION="SolidWorks Assembly" DOCTYPE="3" TYPE="1"
SOURCEREF="C:\Program Files\SolidWorks98plus\SAMPLES\EXAMPLES\Dial
Caliper\Sliding Assembly.SLDASM" MASTERFILENAME="Sliding
Assembly.SLDASM">
<CUSTOMPROP NAME="XMLRef" VALUE="Sliding Assembly" DESCRIPTION="Unique name for
republishing" TYPE="4"/>

<DEPENDENCY FILENAME="D:\Program Files\SolidWorks98plus\samples\examples\Dial
Caliper\Depth Bar.SLDPRT"/>

<DEPENDENCY FILENAME="D:\Program Files\SolidWorks98plus\samples\examples\Dial
Caliper\Face Plate.SLDPRT"/>

<DEPENDENCY FILENAME="D:\Program Files\SolidWorks98plus\samples\examples\Dial
Caliper\Dial Lock Clamp.SLDPRT"/>
</INFOITEM>

<CUSTOMPROP NAME="XMLRef" VALUE="Sliding Assembly" DESCRIPTION="Unique name for
republishing" TYPE="4"/>

<LOOKGRAPHIC FILENAME="Sliding Assembly.SLDASM" ORIGINALREF="C:\Program
Files\SolidWorks98plus\SAMPLES\EXAMPLES\Dial Caliper\Sliding Assembly.SLDASM"/>

<FACE ID="2" NAME="Depth Bar" DESCRIPTION="SolidWorks Part"
NAVIGATIONMODE="1" SPECIALTYPE="1">

<INFOITEM NAME="Depth Bar:SLDPRT" DESCRIPTION="SolidWorks Part" DOCTYPE="2"
TYPE="1" SOURCEREF="D:\Program Files\SolidWorks98plus\samples\examples\Dial
Caliper\Depth Bar.SLDPRT" MASTERFILENAME="Depth Bar.SLDPRT">

<CUSTOMPROP NAME="XMLRef" VALUE="Depth Bar" DESCRIPTION="Unique name for
republishing" TYPE="4"/>

</INFOITEM>

<CUSTOMPROP NAME="XMLRef" VALUE="Depth Bar" DESCRIPTION="Unique name for
republishing" TYPE="4"/>
<LOOKGRAPHIC FILENAME="Depth Bar.SLDPRT" ORIGINALREF="D:\Program
Files\SolidWorks98plus\samples\examples\Dial Caliper\Depth Bar.SLDPRT"/>

</FACE>

<FACE ID="3" NAME="Face Plate" DESCRIPTION="SolidWorks Part" NAVIGATIONMODE="1"
SPECIALTYPE="1">

<INFOITEM NAME="Face Plate:SLDPRT" DESCRIPTION="SolidWorks Part" DOCTYPE="2"
TYPE="1" SOURCEREF="D:\Program Files\SolidWorks98plus\samples\examples\Dial
Caliper\Face Plate.SLDPRT" MASTERFILENAME="Face Plate.SLDPRT">

<CUSTOMPROP NAME="XMLRef" VALUE="Face Plate" DESCRIPTION="Unique name for
republishing" TYPE="4"/>

```

FIG. 3

The screenshot displays the Microsoft Project - SOFTDEV application window. The interface includes a menu bar (File, Edit, View, Insert, Format, Tools, Project, Window, Help), a toolbar with various icons, and a status bar at the bottom showing 'Ready' and keyboard shortcuts (F5, NUM, SCF, OR).


The main workspace is divided into two panes. The left pane shows a task list with the following tasks and their durations:

- 1 Scope
- 2 Determine project scope
- 3 Secure project sponsorship
- 4 Define preliminary resources
- 5 Secure core resources
- 6 Scope complete
- 7 Analysis/Software Requirement
- 17 Design
- 25 Development
- 32 Testing
- 48 Training
- 57 Documentation
- 67 Pilot
- 74 Deployment
- 81 Post Implementation Review

The right pane shows a Gantt chart for the project. The chart displays the timeline from January 2, 1999, to January 23, 1999. The tasks are represented by bars, and the chart shows the sequence of tasks and their durations. The 'Scope' task is highlighted, and its duration is shown as 1/6.

Fig. 4

2025 RELEASE UNDER E.O. 14176



560

550

Fig. 5




Fig. 6




Fig. 7



FIG. 8




Fig. 8




Fig. 9






Fig. 10



450

Fig. 11



**Fig. 12**




Fig. 13




Fig. 14




Fig. 15